## Mattson Joinery - Mattador<sup>™</sup> Approved (FRHL) Fire Rated Hardware List

The following hardware options have been tested and approved for use on Mattson Joinery Mattador™ Fire Door Systems. Competitive prices to supply the following hardware components are available upon request. A cropping service for mortice locks on our CNC routing machine is available, this ensures compliance and saves time on site.



|                |  | 30min        | 60min        |              |   | 30min        | 60min        |
|----------------|--|--------------|--------------|--------------|---|--------------|--------------|
| <b>CLOSERS</b> | Briton 200, 220, 222                       | $\checkmark$ | $\checkmark$ | MORTICE      | Kaba Boyd MS series                           | $\checkmark$ | $\checkmark$ |
|                | Dorma TS68, TS73, TS77, TS83, TS93         | $\checkmark$ | $\checkmark$ |              | Legge 990 series                              | $\checkmark$ | $\checkmark$ |
|                | Guardsman G1300, G1500, G3003              | $\checkmark$ | $\checkmark$ |              | Legge 990 MFE Electronic lock 10mm cable hole | $\checkmark$ | $\checkmark$ |
|                | LCN 4031, 1461, 4000, 4041,524             | $\checkmark$ | $\checkmark$ |              | Lockwood 3500 series                          | $\checkmark$ | $\checkmark$ |
|                | Lockwood 3024, 2024, 7726, 7714, 7724      | $\checkmark$ | $\checkmark$ |              | Novas 6000 series                             | $\checkmark$ | $\checkmark$ |
|                | Ryobi 8853, 1550, 2550, 3550, 4550         | $\checkmark$ | $\checkmark$ | KEY IN KNOB  | Guardsman Key In Knob series                  | $\checkmark$ | x            |
| DOUBLE ACTION  | Briton 2800 adjust/strength Transom Closer | $\checkmark$ | x            |              | Interlock MCN 3082                            | $\checkmark$ | x            |
|                | Dorma BTS85 Floor Spring                   | $\checkmark$ | x            |              | Lockwood 930 series                           | $\checkmark$ | x            |
|                | Dorma RTS85 Transom Closer                 | $\checkmark$ | x            | KEY IN LEVER | Jupiter, Regent                               | $\checkmark$ | x            |
|                | Lockwoood 7750 Tansom Closer               | $\checkmark$ | x            |              | Legge G2 Neptune lever series cylindrical     | $\checkmark$ | x            |
|                | Lockwood 9800N Floor Spring                | $\checkmark$ | x            |              | Schlage A, AL, F Series                       | $\checkmark$ | x            |
|                | Ryobi 202K Floor Spring                    | $\checkmark$ | x            | MISC HARDWAR | RE Briton 376-378 Series Panic Exit Device    | $\checkmark$ | $\checkmark$ |
|                | Ryobi 30-31 Transom Closer                 | $\checkmark$ | x            |              | Briton door co-ordinator                      | $\checkmark$ | $\checkmark$ |
| HOTEL          | CISA CS 9580 Hotel Lock                    | $\checkmark$ | $\checkmark$ |              | Briton magnetic door clamp                    | $\checkmark$ | $\checkmark$ |
|                | Miwa Brantas AL5H                          | $\checkmark$ | $\checkmark$ |              | Eff Eff 10312-10 Power transfer hinge         | $\checkmark$ | $\checkmark$ |
|                | Saflok MT with A59840 mortice lock         | $\checkmark$ | $\checkmark$ |              | Grille - Lorient LVHD Grille                  | $\checkmark$ | $\checkmark$ |
|                | Vingcard                                   | $\checkmark$ | $\checkmark$ |              | Grille - Tenmat infill 350 x 350              | $\checkmark$ | x            |
| <u>TUBULAR</u> | Dalco 12002 Tubular latch                  | $\checkmark$ | $\checkmark$ |              | Guardsman G70 door viewer                     | $\checkmark$ | $\checkmark$ |
|                | Lockwood 530 tubular latch                 | $\checkmark$ | $\checkmark$ |              | Ives-Cor door co-ordinator                    | $\checkmark$ | $\checkmark$ |
|                | Lockwood 8530 headlatch                    | $\checkmark$ | $\checkmark$ |              | Legge 881 Power Transfer Device               | $\checkmark$ | $\checkmark$ |
|                | Miles Nelson 412 tubular latch             | $\checkmark$ | $\checkmark$ |              | Lockwood 160 Door viewer                      | $\checkmark$ | $\checkmark$ |
| ROLLER LATCH   | Dalco 12002 Roller Latch                   | $\checkmark$ | $\checkmark$ |              | Lockwood GI 300 Mag Clamp                     | $\checkmark$ | $\checkmark$ |
|                | Erabus E1511 Roller catch                  | $\checkmark$ | $\checkmark$ |              | Raven RP8                                     | $\checkmark$ | $\checkmark$ |
|                | Kaba Boyd RB111 Roller Latch               | $\checkmark$ | $\checkmark$ |              | Raven RP10                                    | $\checkmark$ | $\checkmark$ |
|                | Miles Nelson 333 Roller catch              | $\checkmark$ | $\checkmark$ |              | Raven RP24                                    | $\checkmark$ | $\checkmark$ |
|                | Sampson 515 Roller catch                   | $\checkmark$ | $\checkmark$ |              | Raven RP38                                    | $\checkmark$ | x            |
|                |  |              |              |              | Raven RP70                                    | $\checkmark$ | x            |
|                |  |              |              |              | Schlage DV004 Door Viewer                     | $\checkmark$ | $\checkmark$ |
| SUMMARY        |  |              |              |              | Securicraft MC 41PB security chain            | $\checkmark$ | $\checkmark$ |

The installation of **non** approved hardware will **void** the rating of the door system.

Mattson Joinery will not be responsible for non compliant door systems.

Fire tags will be issued for each doorset on receipt of the signed and completed (HDL) Hardware Declaration List. All Mattson Joinery Fire Door Systems require the appropriate tags to be affixed to the door leaf and door frame. No modifications / alterations are to be made to the door system after installation of tags. (eg penetrations for pet doors etc). Mattson Joinery fire door approvals allow a maximum 2mm gap between the door leaf and the door frame / jamb A 10mm maximum gap between the underside of the door leaf and the top of the finished flooring is permitted



х

 $\checkmark$ 

 $\checkmark$ 

 $\checkmark$ 

 $\checkmark$ 

 $\checkmark$ 

Trimec electric strike from Interlock

Von Durpin EPT Power Transfer Device

Von Duprin 22-F + 2227-F series Panic Exit Device

Von Duprin 99-F + 9927-F series Panic Exit Device

Von Duprin 88 and 8827 series Panic Exit Device

## Mattson Joinery - Mattador™ Installers (HDL) Hardware Declaration List

JOB #.....

PROJECT NAME;.....

| DOOR # | LEAF TAG # | FRAME TAG # | LATCH TYPE | CLOSER TYPE |
|--------|------------|-------------|------------|-------------|
|        |            |             |            |             |
|        |            |             |            |             |
|        |            |             |            |             |
|        |            |             |            |             |
|        |            |             |            |             |
|        |            |             |            |             |
|        |            |             |            |             |

NOTE; WHEN COMPLETED THIS SCHEDULE BECOMES PART OF THE FIRE DOOR CERTIFICATE, WHICH IT SUPPORTS.

PLEASE CONFIRM THE FOLLOWING;

1) The fire doors identified in this schedule comply with AS/NZS 1905.1 in respect;

| a) Hardware has been selected from the Mattson Joinery Mattador™    | Approved (FRHL) Fire Rated Hardware List. |
|---|---|
| b) Hardware has been installed in accordance with the specific manu | facturers instructions.                   |

- c) Hinges are correctly aligned
- d) The door latches satisfactorily from the fully open position and from any intermediate position
- e) The closer includes cushioned back-checking action to prevent shock when the door is forcibly opened
- f) Floor gap is between 3 10mm from finished floor when door has been installed

| Signature | Company  |
|-----------|--|
| Name      | Postal Address   |
| Date      | PLEASE FAX THE COMPLETED FORM TO 09 2777 479 or post to Mattson Joinery PO Box 76690 Manukau |





Mattson Joinery

